



# IECEX Quality Assessment Report Summary

## INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit [www.iecex.com](http://www.iecex.com)

QAR Ref. No.:	<b>GB/CML/QAR19.0001/07</b>	Page 1 of 1
QAR Free Ref. No.:	<b>R17616A/00</b>	Status: <b>Issued</b>
Details of change:	Recertification audit	Date of issue: <b>2024-08-28</b>
Location(s) audited:	<b>CMP Products Limited</b> 3 Nelson Way Nelson Park East Cramlington NE23 1EB <b>United Kingdom</b>	Valid until: <b>2027-08-29</b>
	<b>CMP Products Limited</b> 36 Nelson Way Nelson Park Way Cramlington NE23 1WH <b>United Kingdom</b>	Audit date: <b>2024-07-26</b>
Issuing ExCB:	<b>CML - Eurofins E&amp;E CML Limited</b>	
Manufacturer:	<b>CMP Products Limited</b> 36 Nelson Way Nelson Park Way Cramlington NE23 1WH	
Location of Manufacturer:	<b>United Kingdom</b>	
Product information:	Cable glands and accessories	
Type of protection:	<b>CMP Products Ltd Ex d, e, t, nR British Engines (India) Pvt. Ltd Ex d, e, t, Trace Heating IEC 60079-30-1</b>	
Related QARs:		
<a href="#">GB/CML/QAR19.0001/00</a>	<a href="#">GB/CML/QAR19.0001/01</a>	<a href="#">GB/CML/QAR19.0001/02</a>
<a href="#">GB/CML/QAR19.0001/03</a>	<a href="#">GB/CML/QAR19.0001/04</a>	<a href="#">GB/CML/QAR19.0001/05</a>
<a href="#">GB/CML/QAR19.0001/06</a>		
Related Certificates (manual insertion)::		
Related Certificates (automatic linking)::		
Related Certificates for previous versions:		
IECEX CML 18.0171U issue: 1	IECEX CML 18.0171U issue: 2	IECEX CML 18.0172 issue: 0
IECEX CML 18.0172 issue: 1	IECEX CML 18.0173X issue: 0	IECEX CML 18.0174 issue: 0
IECEX CML 18.0175X issue: 0	IECEX CML 18.0176U issue: 0	IECEX CML 18.0177X issue: 0
IECEX CML 18.0177X issue: 1	IECEX CML 18.0177X issue: 2	IECEX CML 18.0178X issue: 0
IECEX CML 18.0178X issue: 1	IECEX CML 18.0179X issue: 0	IECEX CML 18.0179X issue: 1
IECEX CML 18.0179X issue: 2	IECEX CML 18.0180X issue: 0	IECEX CML 18.0181X issue: 0
IECEX CML 18.0181X issue: 1	IECEX CML 18.0182X issue: 0	IECEX CML 18.0182X issue: 1
IECEX CML 18.0183X issue: 0	IECEX CML 18.0184X issue: 0	IECEX CML 18.0185U issue: 0
IECEX CML 18.0186U issue: 0	IECEX CML 18.0186U issue: 1	IECEX CML 18.0187U issue: 0
IECEX CML 18.0188U issue: 0	IECEX CML 18.0189U issue: 0	IECEX CML 18.0190X issue: 0
IECEX CML 18.0190X issue: 1	IECEX CML 18.0191X issue: 0	IECEX CML 18.0192X issue: 0
IECEX CML 18.0193X issue: 0	IECEX CML 19.0062X issue: 0	IECEX CML 19.0062X issue: 1
IECEX CML 19.0062X issue: 2	IECEX CML 19.0062X issue: 3	IECEX CML 20.0038X issue: 0
IECEX SIM 15.0002X issue: 1	IECEX SIM 17.0009U issue: 1	IECEX SIM 17.0010 issue: 1

Comments: